

PLANT OPERATIONS—RAVENSWOOD

Safety

No injuries MTD or YTD

Maintenance

- South RBC at secondary sewage plant had a drive sprocket repaired. System up and running.
- GM Baker In to reinstall # 1 blocking deep well pump in pump house.
- Changed oil in Boiler house truck.
- Working on Diesel portable air compressor for use in the plant.
- Rotated Potroom fans and river blowers.
- Changed out Barge Unloading navigational lights.
- Assisted service Tech. on PTC shop air compressor.
- Worked on PTC shop high bay lighting.
- Repairs continue on 2" galvanized water line burst in the Carpenter shop.
- Main gate Simplex fire supervisory panel's Repairs complete.
- Bake Carbon supervisory panel power supply was thought to be bad. Installed new power supply, but did not remedy issue. Have service Tech from Simplex scheduled in to troubleshoot.
- Completed the top southwest strobe light on the 600' stack repairs.
- Armed S41 and S42 sprinkler systems.
- Trash pump used to pump manhole has cracked end housing. Trying to locate repair parts.
- Changed out exhaust fan at primary sewer plant building.
- SD Myers completed annual oil sampling of all plant transformers and OCBs.
- Having some image issues with Barge Unloading Security cameras. Currently troubleshooting problems.
- Continue to make rounds throughout plant.
- Continue daily checks of nitrogen blankets on Rectifier transformers.
- Weekly PM of fire system air compressors.
- Weekly check of oil skimmer.